

# Addendum

---

---

**Title:** Excalibur® Multiport SET-1 DAP Addendum

**Part/Document Number:** 15D08B61-35/A

**Date:** August, 1995

**Supplement to:** Excalibur Multiport SET-1 DAP Installation and Operation Manual

**Part/Document Number:** 15D08B6-1/A

**Date:** March, 1995

---

---

## Manual Addition

Add the following to page 5-4, Step 8:

However, if the DAP has previously been assigned to a TDM bus, such as bus A on time slot 4, and NONE is selected, the previous assignment is not cleared. To clear the previous assignment, perform a factory reset while the bus assignment is set to NONE . (See “System Submenu” in this chapter for instructions.) If you fail to do so, when bus A is reselected, the DAP will automatically be placed back on bus A, time slot 4. If this bus assignment matches that of another DAP in the card carrier, both units will be placed on the same bus time slot causing data corruption on that slot.